


16_01 Adjust Reference Colors

Question:


How can I display all of the reference files in black/ white while leaving the master file in color?

Answer:

Select the reference files in the References dialog box and then choose Settings >>> Adjust Colors.



Display the reference files in white by "Fixed" the Saturation value from 100 to 0.



To undo the changes, set value to 100 (default). Note the "Print Adjusted Colors" option.

Also you can use the Roadway SuppAtta tool to change the line weight to zero for further clarity.

